

ROCKFORD MEMORIAL HOSPITAL – ROCKFORD, IL.

HELICOPTER LANDING PAD ON ROOF OF FOUR STORY BUILDING



The above pictures show the existing / failing coating after it has been removed from the concrete.

The below pictures show the new Citadel Floor Finishing Systems coating. This coating was chosen for its extremely high strength and wear resistance as well as being 100% UV stable. It is exposed to the elements year round so it needed to be able to hold up to changes in temperature and harsh weather.

